16.

UNITED STATES SUBMIT IN TRIPLICATE. DEPARTMENT OF THE INTERIOR verse side)

Form approved, Budget Bureau No. 42-R1424.

5.	LEA	SE	DES	IGNATION	AND	SERIA	L NO.
	MM	-1	031	011			
6.	IF :	IND	IAN,	ALLOTTE	e or	TRIBE	NAME

N.M.

7. UNIT AGREEMENT NAME

Rio Arriba

GEOLOGICAL SURVEY					
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL GAS O	THER	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
J. FELIX HICKMA	N	Clark
3. ADDRESS OF OPERATOR		9. WELL NO.
P. O. BOX 12307	El Paso, Texas 79912	7
	cation clearly and in accordance with any State requirements.	Lindrith Gallup- Dakota West
330'FSL, 23	10'FEL	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 6-T24N-R3W N.M.P.M.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

6983'G.L., 6996'D.F., 6997'K.B.

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

Spud Well 2/13/79

T.D. 280'. Ran 6 joints 8-5/8", 24.0 lb. K-55 casing (265.00') set at 279.00 with 250 sacks Class "B" cement with 3% Calcium 2/13/79 Chloride and 1/4 lb. Flocele per sack. Cement circulated. Pressure test with 500 psig. Test ok.

T.D. 7838'. Ran 209 joints 4-1/2". 10.50 & 11.60, K-55 casing 3/8/79 (7823.90') set at 7833.00' with"

First Stage:

550 sacks 50-50 Pozmix with 6-1/4 lbs. Gilsonite

and 6 lbs. salt per sack.

Second Stage:

125 sacks 65-35 Pozmix (12% Gel) with 6-1/4 lbs.

Gilsonite per sack followed by 50 sacks Neat Cement. Stage collar at 3415

FOR: J. FELIX HICKMAN		MAR CON. COM	
18. I hereby certify that the foregoing is true and correct	President, Walsh Engin.	COL DIST.	
Ewell N. Walsh, P.E.			
(This space for Federal or State office use)			

(This space for Federal or State office use)			
			أحدة أساقات ا
APPROVED BY	TITLE	DATE	
CONDITIONS OF APPROVAL, IF ANY:		·	