Form 3160-5 (November 1983)

## **UNITED STATES**

SUBMIT IN TRIPLICATE.

Budget Bureau No. 1004-0135

	Exp	ires	August	31,	1985	
5.	LEASE	DESI	GNATION	AND	TERIAL	N

(Formerly 9-3)		5. LEASE DESIGNATION AND SERIAL NO. SF 078563			
	BUREAU OF LAND MANAGEMENT				
(Do not	SUNDRY NOTICES AND REPORTS O  use this form for proposals to drill or to deepen or plug bac  Use "APPLICATION FOR PERMIT—" for such proposals		6. IF INDIAN, ALLOTTEE OR TRIB	E NAME	
OIL XXX	GAS WELL OTHER		7. UNIT AGREEMENT NAME	**	
2. NAME OF OPI			8. FARM OR LEASE NAME		
Dannon F	moray Inc. a/o Holcomb Oil s	Coo Inc		24	
3. ADDRESS OF	nergy, Inc. c/o Holcomb Oil & OPERATOR	Gas, Inc.	Grace Federal 9. WBLL NO.		
D O Box	2050 Farmington NM 97400		7		
4. LOCATION OF	2058, Farmington, NM 87499 WELL (Report location clearly and in accordance with any S)	tate requirements.	10. FIELD AND POOL, OR WILDCAT		
See also spa- At surface	ce 17 below.)	•	1		
Unit c:	950' FNL and 1640' FWL		Devils Fork Go 11. SEC., T., E., M., OR BLK. AND SURVEY OR ARMA	arrup	
-			Sec. 24 T24N	R7W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, E	RT, GR. etc.)	12. COUNTY OR PARISH 13. ST	ATE	
	6644 G	R	Rio Arriba	NM	
16.	Check Appropriate Box To Indicate Na		Other Data		
TEST WATE	R SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACTURE T	TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR A	CIDIZE ABANDON*	SBOOTING OR ACIDIZING	ABANDONMENT* X	X	
REPAIR WEI	CHANGE PLANS	(Other)			
(Other)		Completion or Recompl	of multiple completion on Well etion Report and Log form.)		
proposed	OPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent work. If well is directionally drilled, give subsurface locations work.)*	details, and give pertinent dates, ns and measured and true vertice	including estimated date of star al depths for all markers and zon	ting any ies perti-	
	Started plug and abandonment operation				
2.	Set cement retainer at 5200', squeez				
	of 45 sx leaving 5 sx on top of tool	l. Top of cement at $\mathfrak s$	5134'. Reverse mud		
	into hole.				
	Spot 120 sx Class "B" cement from 45				
4.	Spot 136 sx Class "B" cement from 28 1037'.	350' to 1050'. Tag to	op of cement at		
5.	Perforate 4-1/2" casing at 380', cir	culate 133 sx of Cla	ass "B" cement		
	inside and out of 4-1/2" casing from	n 380' to surface.			

- 6. Cut off wellhead 4' below ground level, weld on plate and plug and abandonment marker on August 29, 1989.
- 7. Location has not been rehabilitated; will blade and reseed in spring of 1990.

Apprecial to a diagning of the wolf bors. Liebliky so for bood is equipped until Surkery to the rest of respective.

	1111 - 11		OIL CON. DIV			
18. I hereby certify that the foregoing is true and correct					APPROVED	
SIGNED W.J. Holcomb Cr	TITLE	Agent,	Bannon	Ene	rgy DATE 10-6-89	
(This space for Federal or State office use)  APPROVED BY	TITLE				007 1 2 1989	
CONDITIONS OF APPROVAL, IF ANY:					SW AREX MANAGER FARMINGTON DESCURE AREA	Company of

\*See Instructions on Reverse Side