Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE OCCUPANTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION DESCRIPTION DESCRIPTI
Sl (Do not use	INDRY NOTICES AND REPORTS ON WELLS his form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF Indian, ALLOTTEE OR TRIBE NAME Jicarilla 7. UNIT AGREEMENT NAME
OIL GAS WEIL 2. NAME OF OPERATO		8. FARM OR LEASE NAME
Cotton Pet	roleum Corporation	Apache
4. LOCATION OF WELL See also space 17 At surface	treet, Suite 2200, Denver, Colorado 80202	131 10. FIELD AND POOL, OR WILDCAT Lindrith-Gallup-Dakota- 11. SEC., T., R., M., OB BLK. AND SURVEY OR ARBA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT. GR. etc.) 6908 GR	Sec 4-24N-4W NM PM 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
TEST WATER SHOT FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other) 17. DESCRIBE PROPOSE Work nent to this wo.	PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE PRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) OR COMPLETED OFFRATIONS (Clearly Sit te all pertinent details, and give pertinent diff well is directionally drilled, give subsurface locations and measured and true ve	REPAIRING WELL ALTERING CASING ABANDONMENT® Suits of multiple completion on Well completion Report and Log form.)
6-14-80	Spud Well.	
6-15-80	TD 380', ran 8 joints 8 5/8" 24# casing, set @ 37 250 sacks Class "B" w/3% CaCl, cement circulated	7' with to surface.
7-23 - 80	TD 7462', ran total of 234 joints 4 1/2" 10.5 & 1 Set @ 7583'.	1.6 K-55 casing,

Stage 1: 600 sacks 50-50 Poz, 6 1/4# Gillsonite, 6# salt, 2% gel.

DV @ 4005', 100 sacks Halliburton Lite followed by Stage 2: 600 sacks 5C-50 Poz, 2% gel.



	AUG 4400. OIL CON. COM. DIST. 3
18. I berely correct SIGNED (This space fauged) pr 1980 office use)	TITLE Division Production Manager DATE 7-29-80
COUDITIONS THE MEASUREMENT WAS:	DATE
*C.	o Latroficas on Reverse Side