6 - USGS 1 - McHugh	1 - File
Form 9-331	Form Approved. Budget Bureau No. 42–R1424
Dec. 1973 UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	1 · · · · · · · · · · · · · · · · · · ·
	NM 23038 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	O. H. HODAR, ALCOTTEL OKTRIBE (MAIL
CHARDY NOTICES AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1 oil gas	Federal
1. oil gas well \overleftrightarrow{w} other	9. WELL NO.
2. NAME OF OPERATOR	13
Jerome P. McHugh	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Undesignated -
P O Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 2
below.)	Sec 27 T25N RYZW
AT SURFACE: 990' FSL - 1650' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba NM
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7321 ' GL
TEST WATER SHUT-OFF	EIVED
FRACTURE TREAT	RIVER
SHOOT OR ACIDIZE	0 1981
REPAIR WELL	NOTE: Report results of multiply completion or zone change on Form 9–330.
PULL OR ALTER CASING	- YNOTE: Report results of multiply completion or zone change on Form 9-330.) OLOGICAL SURVEY. ONGTON, N. M.
CHANGE ZONES	OLOGICAL SURVEY. MINGTON, N. M.: OIL CON. OIST. CON.
ABANDON*	Olst COM
(other)	48
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	re all pertinent details, and give pertinent date
including estimated date of starting any proposed work. If well is d	lirectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertiner	nt to this work.)*
Plan to plug and abandon well as follows:	
1. Squeeze perfs 3487-3507' with 20 sx.	
★ 2. Place cement plug from 3150 to 3507'	(Top of Ojo Alamo 3176')
3. Find 4½" csq. free point and shoot of	$oldsymbol{f_{oldsymbol{i}}}$. The second $oldsymbol{i}$ $oldsymbol{i}$ $oldsymbol{i}$ $oldsymbol{i}$
4. Spot cement plug 50' in and 50' out o	of 4½" csg. stub.
来 5. Place 100' cement plug in stem of sur	face csg. The life of the life
e Di Col millo de Los ef confoco con	- with day holo/markor
	3507
* Place cement plug tran 3126 Te	
Perforate 4/2" casing at 262 o	nd place comen plan
inside and outside casing t	to 162, 25 1 2 1 1 2
(,,s),(C an area of)	
	Sal (0)
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	
SIGNED TITLE Agent	DATE 7-9-81
JULY Jacobs	APPROVED
(This space for Federal or State off	fice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	1 1981 - JULA 1 3 1981
NMOCC NMOCC	JAMES F. SIMS
) oh	SIAS SUPERVISOR
*See Instructions on Reverse \$	JIUE ST

*See Instructions on Reverse Side