

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Project Bureau No. 1004-001  
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

SF-078924

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Grace Petroleum Corporation

3. ADDRESS OF OPERATOR

143 Union Blvd - Ste 760, Lakewood, CO 80228

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

970' FSL & 1650' FEL Section 29  
SW SE

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, BT, OR, etc.)

7332' KB, 7329' GL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Connie

9. WELL NO.

#29-1

10. FIELD AND POOL, OR WILDCAT

Escribo-Lybrook

11. SEC., T., R., M., OR BLM, AND  
SQUARE OR AREA

29, T24N-R7W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Temp. Abandon

CELL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Intent Sundry to T&A w/CIBP Connie #29-1 per the following procedure:

1. MIRU service rig. POOH w/183 jts tbg.
2. MIRU WL. PU CIBP & RIH on WL & set @  $\pm$  5800'.
3. Dump bail 5 sxs cmt on top of CIBP.
4. TIH w/tbg to store in hole.
5. Displace & circ. hole full w/inhibited pkr fluid.
6. Clean up & abandon location for T&A status.

"See attached wellbore sketch for details of depths."

RECEIVED  
AUG 12 1987  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

William P. Baswell III

TITLE Operations Engineer

DATE 8/6/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

NMOCG

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

LEASE Connie

LOCATION SW SE Sec. 29, T24N-R7W

COUNTY Rio Arriba

WELL NO. 29-1

FIELD Escrito - Lybrook

STATE New Mexico

TD 6210'

KB 7332'

DF \_\_\_\_\_

GL 7329'

8 5/8" SURF. CSG.

@ 360' WITH

300 SACKS.

183 lbs. 2 3/8" tbg.

TOL @ 1800' 2<sup>nd</sup> stage

OV Tool @ 3201'

TOL @ 5140' 1<sup>st</sup> stage

Gallup, (9/16/80)

5866-84' 59,934 gal +

5912-28' 126,000 # 20/40

5932-54' — 58 Shots

6003-05' — 58 Shots

6007-13' 35,154 gal +

6045-64' 71,000 # 20/40

6092-602' —

6108-14' —

PBTD @ 6190'

4 1/2" CSG. @ 6210'

W/ 860 SXS. 10.5 #/ft

2 stages

COMPLETION INTERVALS:

WELL HISTORY:

(9/16/80) Perfed (6003 - 6114') +

fraced w/ 35,154 gal GWX-7

+ 71,000 # 20/40 sand 46 BPM 3600 psi

Perfed (5866 - 5954') + fraced

w/ 59,934 gal. GWX-7 +

126,000 # 20/40 sand 47 BPM

@ 3300 psi.

IP'd @ 10 BOPD, 290 MCF-PD

on plunger lift

CBL: Good Bond to 5335'

Fair Bond 5335' to 5140'

Good + Fair 3210' to 1800'

REMARKS: