

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☐ GAS WELL ☐ OTHER- Dry Hole

Name of Operator

Jerome P. McHugh

Address of Operator

P O Box 208, Farmington, NM 87499

Location of Well

UNIT LETTER 0 790 FEET FROM THE South LINE AND 1850 FEET FROM

THE East LINE, SECTION 1 TOWNSHIP 24N RANGE 2W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

7315' GL

12. County

Rio Arriba

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐ULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☐CHANGE PLANS ☐OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOB ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:-

1. Spotted 5 sk cement plug 3352' to 2287'.
2. Found free point of casing at 2000' and shot off casing in collar at 1991'.
3. Spotted 15 sk cement plug from 2041-1947'.
4. Spotted 30 sk cement plug from 165' to 25'.
5. Installed dry hole marker with 5 sx cement.

Job complete 8-1-81.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Jim L. Jacobs

TITLE

Agent

DATE 12-10-82

Original Signed by CHARLES W. JOHNSON

TITLE

DEPUTY OIL &amp; GAS IN INSPECTION DIST. #3

DATE