STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

PG. 90 (00HG BEG			
DISTRIBUTI	1	1	
SANTA PE	\vdash	_	
FILE		1	
U.S.O.S.		_	
LAND OFFICE	1		
TRAMSPORTER	OIL	1	
	GAS		
OPERATOR			
PROBATION OF			

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-104 Revised 10-01-78 Format 06-01-83 Page 1

REQUEST FOR ALLOWABLE AND

AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS JAN2 4 1985 OIL COM. DIV. El Paso Exploration Company PO Box 4289, Farmington, NM Reason(s) for tiling (Check proper box) Other (Please explain) Change in Transporter of: Recompletion OII Dry Gas Pool Name Change Change in Ownership Casinghead Gas Order R-7764 Condensate If change of ownership give name and address of previous owner_ II. DESCRIPTION OF WELL AND LEASE Well No. Pool Name, Including Formation Lease No. 29 Jicarilla 123 C West Lindrith Gallup Dakstote (Federa) or Fee Jic.Cbnt.#123 Location 1075 North 5 Line of Section Township 25N -4 W Rio Arriba Range NMPM. County III. DESIGNATION OF TRANSPORTER OF OIL AND NATURAL GAS Name of Authorized Transporter of Off or Condensate Address (Give address to which approved copy of this form is to be sent) Giant Refining Company P. O. Box 256, Farmington, New Mexico 87401 Name of Authorized Transporter of Casinghead Gas or Dry Gas Address (Give address to which approved copy of this form is to be sent) Northwest Pipeline Corporation Box 90, Farmington, New Mexico 87401 Unit 7wp. 25N Rge Is gas actually connected? If well produces oil or liquids, 4 W give location of tanks.

NOTE: Complete Parts IV and V on reverse side if necessary.

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given is true and complete to the best of my knowledge and belief.

If this production is commingled with that from any other lease or pool, give commingling order number:

<u>Drilling</u> Clerk

(Title)

January 25, 1985

(Date)

OIL CONSERVATION DIVISION

SUPERVISOR DISTRUT TITLE

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or despene well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allow able on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner ell name or number, or transporter, or other such change of condition

Separate Forms C-104 must be filed for each pool in multipl-

Form C-104 Revised 10-01-78 Format 08-01-83 Page 2

Designate Type of Completi	ion (Y)	Off Meff	Gas Well	New Well	Workover	Deepen	Plug Back	Same Beaty	Diff. Res'v	
	1011 — (A)	1	•			1	1		DIE ROBIT	
Data Spudded	Date Compl. Ready to Prod.			Total Depth			P.B.T.D.			
Elevations (DF, RKB, RT, GR, etc.)	Name of Pr	oducing Form	lucing Formation		s Pay					
	ļ							Tubing Depth		
riorations				<u> </u>			Depth Casing Shoe			
	 	TUBING,	CASING, ANI	CEMENTI	NG RECORD	<u> </u>		 -		
HOLE SIZE	CASING & TUBING SIZE				DEPTH SE		SACKS CEHENT			
				 						
	 			 -		·	1			
	i			 			<u> </u>			
				1			i			
TEST DATA AND REQUEST OIL WELL			Test must be a sble for this de		,,			qual to or exce	ed top allow	
date First New Oil Run To Tanks	FOR ALLO	18	Test must be a ble for this de		of total volum full 24 hows)			qual to or exce	ed top allow	
TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks ength of Test		K			Method (Flow,			qual to or exce	ed top allow	
Date First New Oil Run To Tanks	Date of Tes	K		Producing M	Aethod (Flow,		(i, etc.)	qual to or exce	ed top allow	
Jate First New Oil Run To Tanks	Tubing Pres	K		Producing M	Aethod (Flow,		Choke Size	qual to or exce	ed top allow	
Jate First New Oil Run To Tanks ength of Test actual Prod. During Test	Tubing Pres	saure		Producing Manager Producing Press	Method (Flow,		Choke Size	qual to or exce	ed top allow	
ength of Test actual Prod. During Test AS WELL	Date of Tes Tubing Pres Oil-Bbis.	saure	- Andrewsky and the second	Producing Manager Producing Press	Aethod (Flow,		Choke Size		ed top allow	