Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

## <u>Jicarilla</u> Contract 123

Do not use this form for proposals to drill or to re-criter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name  Jicarilla Apache		
SUBMIT IN TRIPLICATE -	Other instructions	on reverse side				t, Name and/or N	
Type of Well     Oil Well    X Gas Well    Other      Name of Operator     ENERGEN RESOURCES CORPORATION  3a. Address		3b. Phone No. (include are	8. We Jicar 9. AP		Well Name and No. arilla 123C 28  API Well No. 039-22558		
2198 Bloomfield Highway, Farmington, NM 87401  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  1800 FSL, 1580 FEL, Sec. 6, T25N, R4W, N.M.P.M.  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE				10. Field and Pool, or Exploratory Area W. Lindrith Gallup-Dakota  11. County or Parish, State Rio Arriba NM  PORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION						
X Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection		Reclama Recomp Tempora Water D	lete rily Abandon isposal	Well In  X Other  Downhol  Pay Add	e Commingle	
<ol> <li>Describe Proposed or Completed Operation (clear If the proposal is to deepen directionally or recommendation that the Bond under which the work will be performed.</li> </ol>	plete horizontally, give s	ubsurface locations and meas	sured and true v	ertical depths of	all pertinent m	arkers and zones.	

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

In accordance to Case 12346. Order #R-11363. It is intended to Add the Mesa Verde and downhole commingle it with the West Lindrith Gallup-Dakota as follows:

- 1. MIRU. TOH with tubing
- 2. Set a RBP at 6000'. Pressure test casing to 4000 psi.
- 3. Run a GR-CCL-CBL log across the Mesa Verde.
- 4. Selectively perforate the Mesa Verde from 5060-5680'. Fracture treat the interval.
- 5. Flow back frac and clean out wellbore with air mist.
- 6. Release RBP and TOH.
- 7. TIH and clean out to PBTD. Land tubing at 7600'. Return to Production

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Vicki Donaghey	itle Production Assistant
	Date 9/18/01
O THIS SPACE FOR FEDERAL	OR STATE OFFICE USE
Approved by /si Patricia M. Hester	Title ands and Mineral Resources Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.	or Office