UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved.

Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY		Jicarilla Contract #12
SUNDRY NOTICES AND R	epen or plug back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Use "APPLICATION FOR PERMI"	—'' for such proposals.)	Jicarilla Tribe
OIL GAS OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
James L. Ludwick		Jicarilla
3. ADDRESS OF OPERATOR P.O. Box 70		9. WELL NO.
Farmington, New M		6 - J
 LOCATION OF WELL (Report location clearly and in accord See also space 17 below.) 	ance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface 800°FSL, 1520°FF	17	Ballard Pictured Cliffs
000 rsu, 1520 rs	V_{i}^{\dagger}	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
		Sec. 28, T24N, R5W
14. PERMIT NO. 15. ELEVATIONS (S	how whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6592 Gr.	Rio Arriba New Mexico
6. Check Appropriate Box T	o Indicate Nature of Notice, Repo	t, or Other Data
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASI	NG WATER SHUT-OFF	REPAIRING WELL.
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMEN	T ALTERING CASING
RHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZ	ABANDONMENT*
REPAIR WELL CHANGE PLANS	(Other) Produc	
(()ther)	Completion or	results of multiple completion on Well Recompletion Report and Log form.)
12-23-1981 TD 2295' 1	Unable to run electric locaving hole conditions. PB 2285' Wait on Complet Ran 79 jts, J-55, New, 2-2296' landed @ 2295', cem Class B cement, 2% CaCl, jog. Cement did not circ P.D. @ 5:00 P.M., 12-23-1 Ran Bond log. Cement top	ion , 7/8 casing, 6.5#, ented with 200 sacks, good circulation during ulate. 981.
This space for Federal or State o APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE Agent	DATH 12-29-1981 [GASPTED FOR RECORD

JAN 05 1992 FARMINGTON BISTNICT

*See Instructions on Reverse Side