

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	2. NAME OF OPERATOR Meridian Oil Inc.	3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	5. LEASE DESIGNATION AND SERIAL NO. Jic. Contract 126
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1520'S, 1850'W	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Jicarilla 126 S
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, RT, GR, etc.) 6933' GL	9. WELL NO. 17 (PM)	10. FIELD AND POOL, OR WILDCAT Pic. Cliffs/MV
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-24-N, R-4-W N.M.P.M.			12. COUNTY OR PARISH Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug back this well to the Fruitland Coal in the following manner:

MOL & RU.
Pull 1.66" OD 2.3# Pictured Cliffs tubing.
Release Baker Model "G" seal assembly at 3271' and trip out of hole w/2 3/8" tubing to seal assembly. Lay down seal assembly and trip in hole to 5570'.
Spot 87 sx. cement for a plug from 5732-4735'. WOC 6 hrs and tag plug. Circulate 9.2#/gal mud (25 sx./100 bbls).
Trip in hole and set cement retainer at 3128'. Squeeze 32 sx. cement for a plug from 3258' to 3128'. Release tubing from retainer.
Pressure test casing to 2500 psi.
Reset 3125' of 2 3/8" tubing and plug 1 1/4" part.
Move off location.

This plan is submitted under the extension of work which expires February 8, 1989.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Drilling Clerk

DATE

2-26-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

APPROVED

MAR 16 1988

AREA MANAGER

*See Instructions on Reverse Side

NMOCC