UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 079549
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil	Phillips 32 9. WELL NO.
2. NAME OF OPERATOR	2 2
Joseph B. Gould	10. FIELD OR WILDCAT NAME West Lindrith Gal/Dak.
3. ADDRESS OF OPERATOR Denver, Co	11. SEC., T., R., M., OR BLK. AND SURVEY OR
2829 E. 2nd Ave. Suite 212 80206 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 32, T25N, K3W
below.) AT SURFACE: 2310' FNL & 630' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Rio Arriba New Mexico
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7170' GR (7182' KB)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	(/ 1/0. Gr. (/102. RD)
TEST WATER SHUT-OFF FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING	: 91983
CHANGE ZONES	DELEGIONE DE LOS SINO
(other) Surface casing & cement FARMLES OF E	ESQUECE AREA CONTROL CONTROL
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
Spud well At 12:30 PM. 280' KB. Ran 6 joints R3 casing (255') set a 250 sacks (295 cu. ft.	Co. Rig #9 moved on location Drilled 12-1/4" hole to 8-5/8", 24#, K55, STC, at 269' KB. Cemented with Class "B" w/ 2% CC and Circulated 2 bbls cement at 5:00 PM. Woc 12
Oct. 16, 1983 Pressure test BOP and Drilled out from under	casing to 600 psig. Okay. r surface.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
X	October 17, 1983
(This space for Federal or State of	
APPROVED BY	WOOTL IED LOK KEROKD
	OCT 24 1983
*See Instructions on Reverse	FARMINGTON RESOURCE AREA

Machinist Cont