

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

RECEIVED
FEB 03 1986

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO AN ADJACENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		5a. Indicate Type of Lease State ☐ Fee ☒
2. Name of Operator <i>Cido Oil Co. Bus Rx, Inc</i>		5. State Oil & Gas Lease No.
3. Address of Operator		7. Unit Agreement Name
4. Location of Well UNIT LETTER <i>P</i> <i>670</i> FEET FROM THE <i>S</i> LINE AND <i>525</i> FEET FROM THE <i>E</i> LINE, SECTION <i>4</i> TOWNSHIP <i>25 N</i> RANGE <i>1 E</i> N.M.P.M.		8. Farm or Lease Name <i>Cido</i>
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. <i>46</i>
		10. Field and Pool, or Wildcat <i>E. Puerto Chiquito-Manuel</i>
		12. County <i>Rio Arriba</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) - SEE RULE 1103.

11/5/85 Run Tbg To 2654.88' + set Cement Plug of 13SX from 2654.88' to 2477.09' Pulled up To 2400' + Shut down for Night. *11/6/85* R.I.H. with Tbg, There was No f. H. we mixed 10SX + pumped it from 2654.88' To 2518.75' Pulled up 300' + waited 4hrs Taged top of CEMENT at 2535' That is 117' plug. Pulled Tbg + Perforated at 1890'. Run Tbg To 1890' mixed 17SX + pumped it from 1890' To 1755'. Pulled up 400' + shut down for Night. *11/7/85* Run Tbg in + Taged CEMENT at 1764' Pulled Tbg + Perforated at 1213' Run Tbg in To 1213' mixed 17SX + Pumped. Taged CEMENT at 1112' After waiting 4hrs Pulled Tbg + Perforated at 164' Run Tbg + mixed 18SX + Pumped To Surface + Shut down for Night. we used 25SX cement for job *11/8/85* Run down + Perforated to 1112'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jack Sanders* TITLE *Manager* DATE *4/10/85*
APPROVED BY *Charles Shelton* DATE *2-3-86*
DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE *2/3/86*

CONDITIONS OF APPROVAL, IF ANY: