

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1635' FSL, 915' FEL, Sec. 24, T-25-N, R-6-W, NMPM

5. Lease Number
SF-079177

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

Canyon Largo Unit
8. Well Name & Number
Canyon Largo U #168
9. API Well No.
30-039-23831
10. Field and Pool
Otero Chacra
11. County and State
Rio Arriba Co, NM

2002 APR 17 PM 1:20

070 FARMINGTON, NM

APR 2002

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

3-18-02 MIRU. ND WH. NU BOP. PT BOP. TIH w/gauge ring to 3268'. TOOH. TIH w/2 7/8" CIBP, set @ 3268'. TOOH. TIH, tag CIBP @ 3268'. Load hole w/19 bbl wtr. Establish circ. PT 2 7/8" csg to 500 psi, failed. Plug #1: pump 28 sx Class "B" neat cmt inside 2 7/8" csg above CIBP @ 2252-3268' to cover Chacra interval. TOOH to 1500'. WOC. SDON.

3-19-02 TIH, tag TOC @ 2464'. Load hole w/12 bbl wtr. Circ out bradenhead. PT 2 7/8" csg, failed. Plug #2: pump 28 sx Class "B" neat cmt inside 2 7/8" csg @ 1448-2464' to cover Pictured Cliffs, Fruitland, Kirtland & Ojo Alamo. TOOH. WOC. TIH, tag TOC @ 1731'. TOOH. TIH, perf 3 sqz holes @ 440'. TOOH. Establish circ down 2 7/8" csg & out bradenhead. Plug #3: pump 147 sx Class "B" neat cmt down 2 7/8" csg & out bradenhead. Circ 0.5 bbl cmt to surface. WOC. ND BOP. Cut off WH. Found cmt down 10' in 2 7/8" csg & down 15' in annulus. Pump 15 sx class "B" neat cmt to fill 2 7/8" csg & annulus. Install dry hole marker w/5 sx Class "B" neat cmt. RD. Rig released.

Well plugged and abandoned 3-19-02.

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Oltmann Title Regulatory Supervisor Date 4/16/02
no

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

FOR RECOR

2002

Sm- OFFIC