Form 3160-5 June 1990)	DEPARTMENT OF BUREAU OF LAND		PORM APPROVED Budget Bureay No. 1004-0135 Expires March 31, 1993
		RECEIVED	5. Lease Designation and Serial No. 14-20-0603-1403
SUNDRY NOTICES AND REPORTS ON WELLS TO BE DO not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7 PH 5: 22		6. If Indian, Allottee or Tribe Name Navajo Allotted	
. Type of Well	SUBMIT IN 1		7. If Unit or CA, Agreement Designation
Oil Gas Well [Other		8. Well Name and No.
2. Name of Operator Dugan Production Corp.			Blanco Wash 2
. Address and Telephone No.	_		30-045-22482
P.O. Box 420, Farmington, NM 87499 (505) 325-1821 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1820' FNL - 1520' FWL Sec. 2, T24N, R9W, NMPM			10. Field and Pool or Exploratory Area POTWIN PC EXT.
			Basin-Fruitland Coa 11. County or Parish, State San Juan, NM
CHECK AP	PROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
TYPE OF SU		TYPE OF ACTION	
Notice of Inte	ent	Abendonment	Change of Pleas
Subsequent R	Report	Recompletion Plugging Back	New Construction
•		Casing Repair	Non-Routine Fracturing Water Shut-Off
Π	1		
Final Abando	onment Notice	Altering Casing Other	Conversion to Injection Dispose Water
Describe Proposed or Complex	ed Operations (Clearly state all pertiness		Dispose Water (Note: Report results of multiple completion on W
Describe Proposed or Complex give subsurface locations It is rods &	od Operations (Clearly state all pertinent and measured and true vertical depole intended to plug tubing and fill	Other	Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log form ting any proposed work. If well is directionally dri re by pulling the face with 100 siks 11 be installed.
Describe Proposed or Comples give subsurface locations It is rods & class **	intended to plug tubing and fill BM w/4% gel ceme	Other	Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Log form ting any proposed work. If well is directionally dri re by pulling the face with 100 siks all be installed.
Describe Proposed or Complex give subsurface locations It is rods &	intended to plug tubing and fill BM w/4% gel ceme	Other	Dispose Water (Note: Report results of multiple completion on W Completion or Recompletion Report and Lag forr ting any proposed work. If well is directionally dri re by pulling the face with 100 siks all be installed.

*See Instruction on Reverse Side