South Blanco Federal 25, #5 Sec. 25-T24N-R8W San Juan, NM

## Deviation Record

Depth	<u>Degree</u>
1545'	2-1/2 <sup>0</sup>
2593' 4516'	1/2 <sup>0</sup> 2-3/4 <sup>0</sup>
5312 5445	1-1/2 <sup>0</sup> 3 <sup>0</sup>
5505	2 <sup>0</sup>

This information in the Deviation Record has been furnished to Mesa Petrole/um Cox. by//the drilling contractor and to my knowledge is true and correct. November 2, 1981 Date Division Production Supervisor Rocky Mountain Division State of <u>Colorado</u> City and County of Denver • - -2nd day of November \_\_\_\_, A.D., 1981, personally appeared before me George S. Dixon , who being by me duly sworn, did say that he is the Division Production Supervisor of Mesa Petroleum Co., Rocky Mountain Division, a corporation, and that said instrument was signed in behalf of said corporation by authority of a resolution of its Board of Directors said <u>George S. Dixon</u> acknowledged to me that said corporation executed the same.

Compossion Expires
Too Jenealn Center Bldg