(other)

6 BLM, Fmn l File Form Approved. Budget Bureau No. 42-R1424

UNITED STATES							
DEPARTMENT OF THE INTERIOR							
GEOLOGICAL SURVEY							

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

5. LEASE
NM 21741
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
· · · · · · · · · · · · · · · · · · ·
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Silver Medal
9. WELL NO.
<u> </u>
10. FIELD OR WILDCAT NAME
Undesignated Gallup:
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 27, T24N, RlOW, NMPM
12. COUNTY OR PARISH 13. STATE
San Juan NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6645' GL; 6657' RKB

gas XX other well well 2. NAME OF OPERATOR DUGAN PRODUCTION CORP. 3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AT SURFACE: 620' FSL - 620' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* TD & PBTD

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reached TD of 4952' on 7-31-84.

PBTD = 4910'

Subsurface Safety Valve: Manu. and Type						Set @ Ft.
18. I hereby certify	that the fores	going is true	and corr	rec t	DATE _	AGCERTED FOR RECORD
J J	Jim/L.	Jacobs (1)	nis space	for Federal or State office u	se)	SEP 1 9 1984
APPROVED BYCONDITIONS OF APP	ROVAL, IF AN		TITLE	Ε	DATE	FARMINGTUN RESOURCE AREA
						BY.