TEXACO, INC.

Ref. No. 7 Gas ۲, ۵ 8 5 09-04-90 \_\_TD\_\_\_Cu. ft. ₹ 1st Del. Gas 1st Del. Oil O ₹ Š -Comp. TEST DATA Schd. စုံ Elev. 6024 GL Spd. Cu.ft. W Sx. Pr. Prod. Sim. Acres W/320 Grav. PSI After Days GOR 30-045-28203 Electric Log Well Log C-122 Plat oşe O ۵ Hrs. SICP. Sr. r. C-103 C-104 ΩĮŽ Ş ij F.1c. 1485/S: 1405/W . \* BO/D —MCF/D After z هٔ ا **10PS** Pictured Cliffs Point Lookout Cliff House Greenhorn Ojo Alamo Menefee Fruitland Entrodo Casing S.\_\_ Cag.Perf. Kirtland Chacra Dakota Mancos Gallup

1 27NR 09W UK Oper. Texaco, Inc. BasinFrCoal Co. SJ \$ 11

to. Nellie Platero

Ź



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LAPLATA HIGHWAY FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

I-149-IND-8464 (WC) 3162.3-1.0 (019)

CERTIFIED - RETURN RECEIPT REQUESTED P 253 046 155

DEC. 1 1 1990

Texaco Incorporated 3300 North Butler Farmington, NM 87401

## ABANDONED LOCATION

## Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 7 Nellie Platero, NE/4SW/4 sec. 11, T. 27 N., R. 9 W., San Juan County, New Mexico, lease I-149-IND-8464. As requested by your Sundry Notice on October 29, 1990, the subject APD is rescinded and returned.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely.

Is/ John L. Keller

John L. Keller, Chief Branch of Mineral Resources

## Enclosure

cc: BIA, Window Rock, AZ

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

DECI 2 1990
OIL CON. DIV.
DIST. 3