

(SUBMIT IN TRIPLICATE)

Indian Agency Jicarilla Apache

Tribe of Indians

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee NW/4, NW/4, Sec. 26,  
T-26N, R-5W, N.M.P.M.

Lease No. \_\_\_\_\_  
Rio Arriba County, New  
Mexico - Contract #153

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<b>XX</b>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 11, 1958

Well No. 3-J/ Jicarilla is located 990 ft. from N line and 1190 ft. from W line of sec. 26

NW/4, NW/4, Section 26 T-26N R-5W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Blanco Picture Cliffs Rio Arriba County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6556 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

1. Ran 98 joints  $5\frac{1}{2}$ ", J-55, 15.5# casing - landed at 3162.5 R.K.B. Cemented with 150 sacks with 2% gel on July 6, 1958.
2. Perforated 4 shots per ft. from 3018 to 3058.
3. Sandfraced with 95,000 gallons of water and 100,000 lbs. of sand on July 9, 1958.
4. Ran 96 joints 2", 4.7#, J-55 tubing on July 10, 1958 tubing landed at 3030 R.K.B.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHERN UNION GAS COMPANY

Address 1001 Burt Building

Dallas, Texas

By

Title Drilling Superintendent

