

Section 19

(SUBMIT IN TRIPLICATE)

Indian Agency Maricopa Tribal

Contact # 98

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. Maricopa #98

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY

FARMINGTON, N.M.

September 20, 1957

Maricopa #B

Well No. 4 is located 990 ft. from S line and 1900 ft. from W line of sec. 19

Sec. 19, Section 19
(1/4 Sec. and Sec. No.)

24-N 3-W
(Twp.) (Range)

R.M.P.M.
(Meridian)

Blanco-NT
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7197 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 308' of 10-3/4" Surface Casing in bottom at 308' with 250 cc cement, Circulated. Tested with 700' for 30 minutes before and after drilling Plug. Tested OK. No break.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MARICOPA PETROLEUM COMPANY

Address P.O. BOX 433

MIDLAND, TEXAS

By R.T. OGDEN
Title Division Superintendent



