

OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

June 8, 1965

Pubco Petroleum Corporation
P.O. Box "P"
Aztec, New Mexico

Attn: Glen Rhodes

Dear Glen:

We have received a 1965 deliverability test for your Scott 21 #3 well in L-21-26N-6W. We have checked casing and tubing records against that shown on the test and find the following discrepancies:

The test indicates casing at 2935 and our records indicate 2944. Test indicates pay zone from 2957 to 3016 and our records show 2944 to 3020. Test indicates tubing perforations at 2893 and our records indicate 2941.

Will you please check this information and let us know which is correct.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AUSTIN, TEXAS

MEMORANDUM

TO: DIRECTOR, OIL CONSERVATION COMMISSION
FROM: [Name]
SUBJECT: [Subject]

The following information was received from [Source] regarding [Topic]. It is noted that [Details] and [Details].

It is recommended that [Action] be taken regarding [Topic]. This recommendation is based on [Reasons].

Very truly yours,
[Signature]

[Name]
[Title]

Page 2