

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ 88 APR -5 AM 11:28

2. NAME OF OPERATOR
Meridian Oil INC. FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

3. ADDRESS OF OPERATOR
Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 1650'N, 1190'E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6685'GL

5. LEASE DESIGNATION AND SERIAL NO.
Jic.Cont 110

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla J

9. WELL NO.
11

10. FIELD AND POOL, OR WILDCAT
So. Blanco Pic. Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 18, T-26-N, R- 5-W
N.M.P.M.

12. COUNTY OR PARISH 13. STATE
Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to plug this well in the following manner:

MOL&RU. TOOH w/1 1/4" tbg. TIH w/2 3/8" tbg. to 3260'. Spot 97 sx. cmt. to cover from the Pictured Cliffs perforations to 50' above the Ojo Alamo for a plug from 3299-2519'. (Ojo Alamo - 2569'; top of cement @ 2375'T.S.).

WOC 6 hrs. Tag plug and record top.

Circulate hole w/60 bbls. 9.2#/mud.

Perforate 2 squeeze holes @ 157'. Circulate 45 sx. cement from surface and out bradenhead.

Cut off wellhead and set dry hole marker w/10 sx. cement

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Clerk(CS)

DATE

04-05-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

APR 07 1988

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side