0

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	, Santa	Pe .
Lease No.	W:-035	54
Unit	. <b></b>	
	ilman ok	核产业

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZI	
NOTICE OF INTENTION TO TEST W		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRI	LL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPA	iR
NOTICE OF INTENTION TO SHOOT	OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL O	R ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDO	ON WELL	Report of well shut in	
(IND	CATE ABOVE BY CHECK N	MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		11-24	, 19 <b>.58</b>
/ell No. <b>FC-241</b> is loc	eated 990 ft. fr	from $\begin{cases} N \\ S \end{cases}$ line and $\begin{cases} 990 \\ W \end{cases}$ ft. from $\begin{cases} 88 \\ W \end{cases}$ line	e of sec.
4 mi 14	26N	6yr sourm	
(1/4 Sec. and Sec. No.)	(Twp.)	(Range) (Meridian)	s composer,
uth Blancs (Field)	alo Arrib	nnty or Subdivision) (State or Territ	
		all other important proposed work)	mudding jobs, cement-
	indefinate per	ial other important proposed work)  iad because gas production at propagating expenses.	
ine pressure is not	indefinate per sufficent to	id because gas production at pro-	dgia inoe
ine pressure is not il will be left in	indefinate per sufficent to	ind because gas production at propagating expenses.	went high
ne pressure is not.  il will be left in sireable.	ndefinate per sufficent to condition for	ind because gas production at propagating expenses.	pent sigh
ne pressure is not all will be left in exircable.	ndefinate per sufficent to condition for	ici because gas production at propay operating expenses.  Future operations should that be	pent sigh
ne pressure is not in will be left in Eireable.	ndefinate per sufficent to condition for ork must receive approve.	ind because gas production at propagating expenses.  Puture operations should that be walin writing by the Geological Survey before operations many continues and the continues of the continues	sent high
ne pressure is not in will be left in zireable.  I understand that this plan of wompany Caulkine il	ndefinate per sufficent to condition for ork must receive approve.	ind because gas production at propagating expenses.  Puture operations should that be walin writing by the Geological Survey before operations many continues and the continues of the continues	pent sigh