Porm 9-331 (May 1963)

MELL

SUBMIT IN TRIPLICATE. UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

proved.
Bureau No. 42-R1424. Βu 5. LEASE DE .. NATION AND SERIAL NO.

Contract 115 6. IF INDIAN, ALLOTTEE OR TRIBE MAME

GEOLOGICAL SURVEY					
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

Jicarilla Tribal 7. UNIT AGRESMENT NAME S. FARM OR LBASE NAME

Jicarilla

2-10 10. PIELD AND POOL, OR WILDCAT

9. WELL NO.

2. NAME OF OPERATOR Consolidated Oil & Gas Inc.

GAR X

ADDRESS OF OPERATOR

P.O. Box 2038, Farmington, New Mexico

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

Bee also space 17 below.)

At surface

1650' FNL & 990' FWL of Section 10, Township 26 North, Range 3 West, NMPM.

Pictured Cliff & Dakota 11. SEC., T., R., M., OR BL. BURYEY OR AREA Sec. 10 Twn 26 North, Range

14. PERMIT NO.

PRT WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

DEPAIR WELL

15. SLEVATIONS (Show whether DP. HT, GR, etc.)

3 West NMPM. 12. COUNTY OR PARISH 18. STATE

New Mex. Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

PULL OR ALTER CASING MULTIPLE COMPLETE

ABANDON* CHANGE PLANS

REPAIRING WELL WATER SHUT-OFF PRACTURE TREATMENT

ALTERING CARING ABANDONMBNT*

(Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)

7

(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clenrly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.) *

Squeezed 100 sacks regular cement into Dakota formation at 7996. Placed 12 sack cement plug across Fictured Cliff at 37431. Pumped 35 sack cement plug at 1445' - 7" cut off stub. Put 35 sack cement plug at base of 9 5/8" surface at 290'. Put 10 sacks in top of 9 5/8" and around marker. Erected and welded in appropriate marker. Cleaned and leveled location as required.



JUN 2.1 1965 S. OLOCOCICAL SURVEY

18. I hereby certify that the foregoing is true and correct

Production Foreman TITLE

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side