

Form 9-381a  
(Feb. 1961)

			<b>X</b>

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **079161**  
Unit **Candado**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<b>Subsequent Report of Sand-Oil Treatment</b> <b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**November 30th**, 19**56**

Well No. **14** is located **1190** ft. from **N** line and **390** ft. from **E** line of sec. **10**

**NE/4 NE/4 Sec. 10** **26N** **7N** **N. H. P. M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**South Blanco** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6692** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**11-25-56** TD 2905'. Flowing 83 MCF/day. Sand-oil treated from 2838' to 2905' with 17,000 gallons diesel oil and 30,000# sand, flushed with 3,000 gallons diesel oil. Breakdown pressure 900#, treating pressure 1350#, final pressure 900#, injection rate 36.5 barrels per minute. After 18 hours flowing 2,902 MCF/day.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **CANDADO PRODUCTION COMPANY**  
Address **716 First National Bank Bldg.**  
**Phoenix, Arizona**

By **George D. Hoyer**  
Title **President**

