

(SUBMIT IN TRIPLICATE)

Approval copies 25 or less  
Indian Agency JicarillaUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYAllottee \_\_\_\_\_  
Lease No. Tribal 101

	2	
		0

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 20, 1963

Huron  
Well No. 4-2 is located 990 ft. from N line and 1190 ft. from E line of sec. 2

SE 2 26N 4W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Basin Dakota Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

Tapacito Pictured Cliffs

The elevation of the derrick floor above sea level is 7171 ft. KB  
7159 GL

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 10/7/63. Drilled 17" hole to 303' KB, set 12-3/4" casing at 303' KB and cemented with 275 sx. of regular, 2% CaCl<sub>2</sub>. Bumped plug 10/8/63 with 800 psi - held okay. Drilled 10-3/4" hole, set 8-5/8" casing at 4175' KB, cemented with 171 sx 50-50 Pozmix, 4% gel and 90 sx. regular, 2% CaCl<sub>2</sub>. Bumped plug 10/17/63 with 1500 psi, held okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Huron Drilling Company, Inc.Address Suite 7151575 Sherman StreetDenver, Colorado 80203By [Signature]Title President