

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO


(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079361
Unit 079302-A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	X	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)



June 24, 1952

Well No. 3 is located 1265 ft. from N line and 1090 ft. from E line of sec. 6

SE 1/4 Sec. 6 (1/4 Sec. and Sec. No.) 26N (Twp.) 6E (Range) 10W (Meridian)
Wildcat Canyon (etc) (Field) Bio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the ^{ungraded}~~corner floor~~ _{ground} above sea level is 5522 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 13 3/8 inch Rotary hole to 110 feet. Set 100 feet of 10 3/4 inch surface casing. Circulate out with 100 sacks.

Drill 3 3/4 inch hole to 3100' or top of Pictured Cliff - set 20#, 7 inch with 100 sacks.

Drill 6 inch hole with Cable Tools from 3100 to 3200 feet.

Shoot open hole, tamped, with 300 quarts Nitro Gel.

WIRED R. R. SPURRIER, SANTA FE, FOR APPROVAL UNORTHODOX LOCATION 6-26-52.
RECEIVED APPROVAL BY WIRE 6-27-52, SIGNED R. R. SPURRIER.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company Ralph A. Johnston

Address P. O. Box 313

Farmington, New Mexico

By James W. Copeland

Title Supt.



DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPlicate)

Land Office _____
Lesse No. _____
Date _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF PULLING OR ALTERING CASING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, (N) FOR NEW, (A) FOR ALTER, (P) FOR PULL, (S) FOR SHOOT, (R) FOR REPAIR, (D) FOR DRILL, (C) FOR CHANGE, (T) FOR TEST, (W) FOR WATER SHUT-OFF, (O) FOR OTHER

19

Well No. _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

(Field) _____ (County or Subdivision) _____ (State or Territory) _____
(Twp.) _____ (Range) _____ (Meridian) _____

The elevation of the datum face above sea level is _____ ft.

DETAILS OF WORK

(State names of and exposed depths to objective sands; show sizes, weights, and lengths of pebbles and grains; indicate mudlogging jobs, cementing, etc., and all other important proposed work)

Company _____
Address _____
By _____
Title _____