



STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334 6174

June 29, 1993

Mr. Tom Mullins
Meridian Oil Inc
PO Box 4289
Farmington NM 87499

RE: SJU 27-5 #24A, I-32-27N-05W
Jicarilla West #9, K-06-26N-05W

Dear Tom:

Both 1992 and 1993 Packer Leakage Tests on the referenced wells indicate packer or tubing leaks. Meridian Oil Inc was directed to initiate remedial activity on both wells in 1992. I have had no reply from your office and apparently no action has been taken. I realize you have many recompletions, workovers and P&A's, plus your bradenhead pressure remediation program and probably do not consider these wells to be top priority. However, as they have been carried over from last year, I urge you to move on them as soon as possible to prevent stronger action from being necessitated.

Yours truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/sh

xc: Well Files