

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3a. Address

2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No. (Include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

900' FNL, 990' FEL, Sec. 6, T26N, R5W, N.M.P.M.

5. Lease Serial No.

Jic Cont 152

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.

Jicarilla West 8

9. API Well No.

30-039-06729

10. Field and Pool, or Exploratory Area

Blanco MV/Basin DK

11. County or Parish, State

Rio Arriba NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

cement

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

12/3/01 MIRU.

12/4/01 RU Computalog. RIH and set RBP at 3350'. Ran CBL/CCL from 3330' to TOC at 1800'. Perforate 4 squeeze holes at 1770'. TIH with packer, set at 1500'.

12/5/01 RU Halliburton. Squeeze with 250 sks "B" (295 cu ft). RD Halliburton

12/6/01 TOH with packer. TIH with bit.

12/7/01 Tag cement at 1548'. Drill out cement. TOH. Run CBL from 1900' to surface, TOC at 1460'. Test casing to 750 psi - OK.

12/8/01 Check pressure on bradenhead 0 psi.

12/10/01 Bradenhead pressure 35 psi. Perforate 4 sq holes at 620'. TIH, set packer at 320'.

12/11/01 RU Halliburton. Squeeze with 235 sks "B" (277 cu ft), circulate 1.5 bbls cement to surface.

12/12/01 TOH with packer. TIH with bit, tag cement at 569'.

12/13/01 Drill cement to 625'. Test casing to 500 psi for 30 mins - OK. TOH with bit. TIH with RBP retrieving tool.

12/14/01 TOH with RBP. TIH with 2 3/8" tubing, land at 7453'. RDMO.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Don Graham

Title

Production Superintendent

Date 1/7/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Patricia M. Newlin

Title
Lands and Mineral Resources

Date JAN 14 2002

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office