


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079364
Unit Rincon



RECEIVED
SUNDRY NOTICES AND REPORTS ON WELLS
OCT 7 1958

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 57 is located 990 ft. from N line and 990 ft. from E line of sec. 1
SW NE NE Sec. 1 26N 7W RMPH
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco - Dakota Rio Arriba New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6602 ft. MB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6/16/58 the 10/64" bottom hole choke was pulled from 7270'. On 6/17/58 an Otis type "BN" 16/64" bottom hole choke was set at 7322'. The larger bottom hole choke increased the production from about 500 MCF/D to about 700 MCF/D.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXAS NATIONAL PETROLEUM CO.,

Address 1054 W. Broadway

Farmington, N. M.

By D. E. A. Johnson
 Title D. E. A. Johnson
Area Manager