0

CSUDMIT	 TRIPLICATE)

United St ates				
DEPARTMENT	OF.	THE	INTERIOR	
GEOLOGICAL SURVEY				

Indian Agency Jicarilla
Allotton Tribal 101
Lease No.

SUNDRY NOTICES AN	D REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REMAR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL	NUV 12 13 03
	H. O. OFOLOGICAL GUIDVEY
(Indicate above by Check Mark nat	U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO November 8 1963
	17
Huron Well No. 2-2 is located 990 fc. from	$\begin{bmatrix} N \\ S \end{bmatrix}$ line and 890 ft. from $\begin{bmatrix} K \\ W \end{bmatrix}$ line of sec. 2
NW 2 26N 4	4W NMPM Range) (Meridian)
Basin Dakota Rio Arr	iba New Mexico Ol. TVI
(Field) (County or S Tapacito Pictured Cliffs	
Tapacito Pictured Cliffs	; 6964 fr KB NOV1 3 1963
The elevation of the derrick floor above sea level	40E2 C1
Peasile	OF WORK
	\ Dist. 3
ing points, and all other	weights, and lengths of proposed casings; indicate mudding jobs, cement- r important proposed work)
set at 306' KB, cemented with 300 sx at 10:00 A.M. 9/4/63 - held okay. D	ed 17" hole to 310', ran 12-3/4" casing, of regular with 2% CaCl ₂ . Plug down rilled 10-5/8" hole to 4000'. Ran 8-5/8" 25 sx. of regular and 100 sx. of regular 00 psi at 1:45 A.M., 9/12/63 - plug held
•	
I understand that this plan of work must receive approval in wri	iting by the Geological Survey before operations may be commenced.
Company Huron Drilling Company	, Inc.
Address Suite 715	26 241
1575 Sherman Street	By // XI
Denver, Colorado 80203	Title President
U. S. GOVERNMENT PRI	KYING OFFICE 16-8437b-8