

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

5F-079162

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Comm. Agree. No. SW-154

8. FARM OR LEASE NAME

Federal Burns TD

9. WELL NO.

1-5

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5-26N-7W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL WELL

2. NAME OF OPERATOR

International Oil & Gas Corporation

3. ADDRESS OF OPERATOR

825 Petroleum Club Building
Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FNL, 790' FEL Sec. 5-26N-7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6640' Gr., 6652' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 7-7/8" hole to 7390' TD.

Ran 4 1/2" OD - J-55 - ST & C casing as follows:

11.6# from surface to 46' (2 joints)

10.5# from 46' to 6680' (204 joints)

11.6# from 6680' to 7390'RKB (22 joints).

Cemented as follows:

1st stage: Thru casing shoe @ 7390' RKB w/200 sacks
40% Diacel "D" followed by 100 sacks Incor
neat cement. Plug down 7:30 P.M. on June
19, 1964.

2nd stage: Thru Baker multiple stage cementing collar
@ 2942' w/50 sacks Class "A" oil-cement.
Closed stage collar w/250 sacks "A" oil-cement.
on June 19, 1964.

WOC.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE

Engineering Manager

DATE June 26, 1964

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE


DATE

*See Instructions on Reverse Side

RECEIVED

JUN 26 1964

U. S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.