SHOOT OR ACIDIZE

REPAIR WELL

ABANDON*

CHANGE PLANS

SHOOTING OR ACIDIZING

Form approved.

(May 1903)	DEPARTMENT OF THE INTERIC GEOLOGICAL SURVEY	OR verse side)	5. LEASE DESIGNATION AND BERIAL NO. SF-079162 6. IF INDIAN, ALLOTTED OR TRIBE NAME
SUNDI (Do not use this for	- y 4 y		
OIL GAS X	other Shut in		7. UNIT AGREEMENT NAME
DEPCO, Inc.			Miles Federal
3. ADDRESS OF OPERATOR 1025 Petrole 4. LOCATION OF WELL (Rep See also space 17 below. At surface	cum Club Building, Denver ort location clearly and in accordance with any S	r, CO 80202 State requirements.	1 10. FIELD AND FOOL, OR WILDCAT Largo Gallup
710' FNL, 17	50' FWL		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA C, Sec. 5, T26N, R7W
14. PERMIT NO.	GR 6598, KB 60		Rio Arriba NM
16.	Check Appropriate Box To Indicate No		
NO: TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The Miles Federal No. 1 is a dual completed well. The Gallup zone was produced through the tubing-casing annulus, and the Dakota zone produces through the tubing. The Gallup zone has been in a temporary abandoned status since July, 1971.

DEPCO, Inc., plans no work on the Gallup zone until work is needed on the Dakota zone.

DEPCO, Inc., requests approval to retain temporary abandoned status.

18. I hereby certify that the foregoing is true and correct	TITLE _	Dist.	Prod.	Supt.	раты 2-1-75
(This space for Federal or State office use) APPROVED BY	TITLE _				DATE
CONDITIONS OF APPROVAL, IF ANY:					