Firm (100=5 ,wotember 1 053) Formerly 9=301;

UNITED STATES DEPARTMENT OF THE INTERIOR verse side:

SUBMIT IN TRIPLICATES Of the Submit of the S

Budget Barcua No.	
Expires August 31,	1985
LEASE DESIGNATION AND	SERIAL.

BUREAU OF LAND MANAGEMENT

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS -

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir

6 IF IBDIAN, ALLOTTEE OR TRIBE NA

i		a 1920 - 17.0: 55	7. UNIT AGREEMENT NAME
OIL GAS X	OTHER		_
2. NAME OF OPERATOR		120 FAS 1.21 U.I. 11.7	8. FARM OR LEASE NAME
DEKALB Energy Com	oany		Miles Federal
3. ADDRESS OF OPERATOR			9. WBLL NO.
1625 Broadway Den	ver. CO 80202		1
4. LOCATION OF WELL (Report le	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.		
See also space 17 below.) At surface			Largo Gallup
710' FNL & 1750'	710' FNL & 1750' (NE/4 NW/4) Section 5, T26N-R7W		
			Sec. 5, T26N-R7W
14. PERMIT NO.	15 ELEVATIONS (Show whe	ether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
30-039-06759	6598' GR	6610' KB	Rio Arriba New Mexico
16. Ch	eck Appropriate Box To India	rate Nature of Notice Report	or Other Data

NOTICE OF INTENTION TO:				:	SUBSEQUENT EMPORT	r of:
			r —			
TEST WATER SHUT-OFF	1	PULL OR ALTER CASING			WATER SHET-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE			PRACTURE TREATMENT	ALTEBING CASING
SHOOT OR ACIDIZA		ABANDON*	i — - :		SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	<u>.</u>	CHANGE PLANS			(Other) Request for Temp.	Abnd Status XX
(Other)	_		- <u> </u>		Norm: Report results of multiple Completion or Recompletion Repor	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The Miles Federal No. 1 is a dual completed well. The Gallup zone was produced through the tubing-casing annulus, and the Dakota zone produces through the tubing. Gallup zone has been in a temporary abandoned status since July, 1971.

DEKALB Energy Company, plans no work on the Gallup zone until work is needed on the Dakota DEKALB Energy requests approval to retain temporary abandoned status. zone.

> OIL COIL DIV. DIST

18. I hereby certify that the foregoing is true and correct TITLE District Superintendent August 27, 1991 SIGNED (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side PARTY .