

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 3249, Englewood, CO 80155

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FSL 1650' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
Contract #109

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Dulce, NM

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla B

9. WELL NO.
6

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 22, T26N R5W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6594' gr.

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Repair tubing leak

☐

☐

☐

☐

☐

☐

☐

☐

☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/25/82 - RIH w/tbg and overshot. Set dn on fish. Couldn't get into tool. POOH w/tbg and overshot. RIH w/impression block. Had flare on top of tbg. RIH w/tbg and flat btm mill. Milled 6". POOH w/tbg and mill. RIH w/tbg and overshot. Set dn. Took a good bite. Pld 45,000#. Started up hole, pld up 5 stands.

6/26/82 - POOH w/balance of tbg and overshot. Had 13 jts, drug all the way. Badley corkscrewed. RIH w/flat btm mill. Milled 9". POOH w/tbg and mill. RIH w/tbg and overshot. Tbg still crooked, wouldn't go dn far enough to get a good bite. POOH w/tbg. Stood it back.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Denise Wilson TITLE Production Analyst DATE 6/30/82

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUL 07 1982

FARMINGTON DISTRICT
BY SPK *See Instructions on Reverse Side

NMOCC

