UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Tenneco Oil Company	Jicarilla B
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Dulce, NM 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Jicarilla B
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR	Jicarilla Dulce, NM 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Jicarilla B
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Jicarilla B
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR	8. FARM OR LEASE NAME Jicarilla B
1. oil gas well other 2. NAME OF OPERATOR	Jicarilla B
1. oil gas well other 2. NAME OF OPERATOR	Jicarilla B
well well well other 2. NAME OF OPERATOR	
2. NAME OF OPERATOR	9. WELL NO.
	6
	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
Box 3249 Englewood, Co. 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
below.)	Sec. 22, T26N, R5W
AT SURFACE: 1650' FSL, 1650' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba, NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
mp.	6594' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	553warr n
PULL OR ALTER CASING	997 (NOTE: Report results of multiple completion or zone change on Form 9–330.)
MILL TIPLE COMPLETE	
CHANGE ZONES	
ABANDON*	
(other) Repair Tubing Leak	*
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly straincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin	ate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
7/6/82 POOH. RIH W/fishing assembly and over $0.65,000$ for $1-\frac{1}{2}$ hrs. Could not move fish. NDBOP. NUWH. RDMOSU.	
	·
	Set @ Ft.
Subsurface Safety Valve: Manu. and Type	Set @ rt.
18. I hereby certify that the foregoing is true and correct	
	nalyst page July 8, 1982
SIGNED (COULD (CLESSOFITE Production Ar	
SIGNED (This space for Federal or State	
(This space for Federal or State	office use)
(This space for Federal or State	

*See Instructions on Reverse Side

NMOCC

@ 7100'.