

Form 5-19
May 1967

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

U.S. GEOLOGICAL SURVEY
BUREAU OF LANDS
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Cont. ¹⁰⁶ 8	
2. NAME OF OPERATOR Tenneco Oil Company		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 720 So. Colorado Blvd., Denver, Colorado 80222		8. FARM OR LEASE NAME Jicarilla C	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850' FN and 790' FW, Unit E		9. WELL NO. 8	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7202' GR	
		10. FIELD AND TOOL OR WILDCAT Blanco Mesaverde Basin Dakota	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 18, T26N, R5W	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) ☐ Commingle	(Other) ☒ X	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROCEDURE:

1. Rig up wireline tools and open sliding sleeve in 2-3/8 tbg. Pkr @ 7925'.
2. Swab well in.
3. Return well to production with both zones producing up tbg.
4. Clean up location.

This work to be done in compliance with New Mexico Oil Conservation Commission Order #R-5707 (4/18/78)



RECEIVED

MAY 18 1978

U.S. GEOLOGICAL SURVEY
BUREAU OF LANDS

18. I hereby certify that the foregoing is true and correct.

SIGNED Curly Hattness TITLE: Administrative Supervisor DATE 5/18/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

ST

*See Instructions on Reverse Side

Okal