

UNITED STATES
DEPARTMENT OF THE INTERIOR



SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)

5. Lease

NM-03554

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

06

1. Oil Well ☐ Gas Well ☐ Other ☐
GAS WELL

070 FARMINGTON, NM

BREECH "C" 144

2. Name of Operator:

Caulkins Oil Company

9. API Well No.

30-039-08156-00C1

3. Address of Operator:

(505) 632-1544

P.O. Box 340, Bloomfield, NM 87413

10. Field and Pool, Exploratory Area

DAKOTA, TOCITO, MESA VERDE

4. Location of Well (Footage, Sec., Twp., Rge.)

990' F/N 1090' F/E

SEC. 12-26N-6W

11. Country or Parish, State

Rio Arriba Co., New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment Notice

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut-Off

☐ Altering Casing

☐ Conversion to Injection

☐ Other Commingle Well

☐ Dispose Water

17. Describe Proposed or Completed Operations:

4-26-99 Moved rig and air package to location. Rigged up Triple P rig #1.
Nipped up wellhead.
T.O.H. with 176 joints 2 3/8" tubing.
T.I.H. with 2 3/8" tubing and retrieving head.
Tagged sand at 110' above retrievable bridge plug set at 5717'.
Circulated tubing down with air to retrievable bridge plug. Plug came free.
Continued in hole with tubing to 6950'.

RECEIVED
MAY 20 1999

OIL CON. DIV.
DIST. 3

4-27-99 T.I.H. and unloaded hole with air package.
Latched onto retrievable bridge plug and tripped out of hole (recovered bridge plug).
T.I.H. with tubing and retrieving head.
Tagged sand at 60' above retrievable bridge plug set at 7037'.
Circulated tubing down with air package.
Latched onto retrievable bridge plug. T.O.H. plug not recovered.

(Continued on page 2)

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED: Robert L. Verquer
ROBERT L. VERQUER

TITLE: Superintendent

DATE: May 10, 1999

ACCEPTED FOR RECORD

APPROVED BY: _____
CONDITIONS OF APPROVAL, IF ANY

TITLE: _____

DATE: MAY 1 1999

FARMINGTON FIELD OFFICE
BY: _____

4-28-99 T.I.H. with tubing.
Chased bridge plug down to top of model "D" packer at 7436'.
Latched onto retrievable bridge plug and tripped out of hole (recovered bridge plug).
T.I.H. with washover shoe to drill out model "D" packer set at 7436'.

4-29-99 Continued in hole with mill shoe.
Drilled over model "D" packer set at 7436'.
Chased packer past bottom perforation at 7685'.
Cleaned out hole and left packer at 7698'.

4-30-99 T.O.H. with tubing and washover shoe.
T.I.H. in hole with 2 3/8" production string.
Landed on doughnut at 7603' with seating nipple 1 joint off bottom.
Nippled up wellhead.
Rigged down.

5-10-99 First delivered commingled Dakota – Tocito – Mesa Verde production to Williams Field Services at 1:00 p.m.