

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
2140' FNL, 1270' FWL, Sec.8, T-26-N, R-4-W, NMPM

5. Lease Number
Jic Contract 119
6. If Indian, All. or
Tribe Name
Jicarilla Apache
7. Unit Agreement Name
8. Well Name & Number
Jicarilla 119 N #13
9. API Well No.
30-039-20009
10. Field and Pool
Tapacito Pictured Cliffs
11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

11-2-95 MIRU. ND WH. NU WH. Pump 5 bbl wtr down csg, no blow out bradenhead. Establish injection into Pictured Cliffs perfs. SDON.

11-3-95 ND WH. NU BOP. PT BOP. TIH to 3106'. Plug #1: pump 6 sx Class "B" cmt @ 2888-3106'. TOOH to 2852'. WOC. Load hole. PT csg to 500 psi/5 min, OK. TIH, tag TOC @ 2997'. Perf 4 sqz holes @ 2990'. TOOH. Attempt to establish injection. Perf 4 sqz holes @ 2940'. Attempt to establish injection. TIH to 2994'. Plug #2: pump 5 sx Class "B" cmt @ 2813-2994'. TOOH to 2198'. Perf 4 sqz holes @ 2198'. Establish injection. Plug #3: pump 28 sx Class "B" cmt below cmt retainer outside csg, left 9 sx Class "B" cmt inside csg @ 1871-2198'. SD for weekend.

11-6-95 TIH, tag cmt @ 1996'. TOOH. Load hole. Perf 2 sqz holes @ 196'. Establish circ down csg & out bradenhead w/3 bbl wtr. Plug #4: pump 61 sx Class "B" cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Install dry hole marker w/8 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 11-6-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 11/14/95

(This space for Federal or State Office use)
APPROVED BY [Signature] Title Chief Lands and Mineral Resources Date APR 15 1996

CONDITION OF APPROVAL, if any: