

OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD

AZTEC, NEW MEXICO

July 19, 1967

Mr. K. E. Roddy  
Southern Union Production Company  
P. O. Box 808  
Farmington, New Mexico

Re: Southern Union Production Co.  
Jicarilla A #8  
E-23-26N-4W

Dear Mr. Roddy:

The packer-leakage test for the subject well does not prove zone separation.

Please cause the well to be scheduled for retest. Such test to be conducted in a manner to prove separation or communication.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick  
Engineer, District #3

ARK:mc

COPY

OIL CONSERVATION COMMISSION  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO

MEMORANDUM

TO: Mr. [Name]

FROM: Mr. [Name]

SUBJECT: [Subject]

[Faint text block]

[Faint text block]