



Southern Union Exploration Company  
P.O. Box 1104  
Farmington, New Mexico 87401  
(505) 425-1104

January 3, 1985

Mr. Frank Chavez  
New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, NM 87410

Re: Jicarilla E #8  
Jicarilla Contract # 104  
1190' FNL & 1480' FWL  
Sec 15-T 26N-R 4W  
Rio Arriba Co., NM

Dear Mr. Chavez

At the end of August, 1984, the above referenced well was worked over. The commingled Gallup and Dakota tubing was altered with packers and a down-hole sliding sleeve to allow single or aggregate production of the Gallup and/or Dakota zones. The Dakota zone was left open for production. The Gallup was isolated behind the sliding sleeve tool, closed in.

Thank you

Jeffrey J. Bollschweiler  
Division Drilling and Production Engineer

cc: Stella Whitaker

JJB:jab

RECEIVED  
JAN 04 1985  
OIL CON. DIV.  
DIST. 3