

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R-1424.

5. LEASE DESIGNATION AND SERIAL NO.

**Contract #105**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**Jicarilla Apache**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**Jicarilla #1\***

9. WELL NO.

**11**

10. FIELD AND POOL, OR WILDCAT

**Tapacito Pictured Cliffs  
Basin, Dakota**11. SEC., T., R., S., OR BLK. AND  
SURVEY OR AREA**Sec. 14, T-26N, R-4W****S.M.P.M.**

12. COUNTY OR PARISH

**San Juan**

13. STATE

**New Mexico****SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

**Southern Union Production Company**

3. ADDRESS OF OPERATOR

**P. O. Box 808, Farmington, New Mexico 87401**4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface**1550 feet from the South line and 1650 feet from the East  
line.**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**7134 Ungraded ground level**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) **Spudding**

REPAIRING WELL


ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spudded 13-3/4" surface hole 4:00 P.M., July 20, 1968. Drilled to T.D. of 389 ft. S.K.B.
2. Ran 12 jts. of 10-3/4", 32.75', H-40 surface casing. Landed at 385 ft. S.K.B. Cemented w/225 sacks regular cement w/2% Calcium Chloride and 1/4# flo-sol/sk. Plug down 1:00 A.M. July 21, 1968. Cement Circulated to surface.
3. Rippled up and pressure tested surface casing and blowout preventer to 800 psi for 10 minutes. Test OK.
4. Drilled out from under surface casing with 9-7/8" hole on July 21, 1968.



RECEIVED

JUL 24 1968

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED **GILBERT D. NOLAND, JR.**TITLE **Drilling Superintendent**DATE **July 23, 1968****Gilbert D. Noland, Jr.**  
(This space for Federal or State office use)APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

887-881

