

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

CONTRACT #150

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

JICARILLA APACHE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

JICARILLA "G"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

BLANCO MESAVERDE
BARIN DAKOTA11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASEC. 2, T-26N, R-5W,
N.M.P.M.

12. COUNTY OR PARISH

RIO ARriba

13. STATE
NEW MEXICO1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

SOUTHERN UNION PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

1625 FT. FROM SOUTH LINE & 915 FT. FROM EAST LINE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6700 FT. R.K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

SUPPLEMENTARY HISTORY

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. DRILLED 9-7/8" HOLE WITH MUD TO T.D. OF 3610 FT. R.K.B. RAN 116 JOINTS OF 7-5/8", 26.40#, J-55 CASING. LANDED AT 3597 FT. R.K.B. CEMENTED WITH 600 CU.FT. CEMENT. PLUS DOWN AT 2:50 A.M. 8/6/69.
2. NIPPLED UP AND PRESSURE TESTED 7-5/8" CASING AND B.O.P. TO 1500 PSI FOR 15 MIN. TEST OK.
3. GAS DRILLED 6-3/4" HOLE TO T.D. OF 7835 FT. R.K.B. REACHED T.D. 8/13/69.
4. RAN 135 JTS. (4418 FT.) OF 5-1/2", 15.50#, J-55 CASING AS LINER. BOTTOM OF LINER AT 7834 FT. R.K.B. TOP OF LINER AT 3416 FT. R.K.B. CEMENTED LINER WITH 200 CU.FT. CEMENT. PLUS DOWN AT 4:00 A.M. 8/13/69.
5. MOVED IN COMPLETION RIG 9/3/69. RAN 2-3/8", E.U.E. TUBING AND CLEANED OUT TO P.B.T.D. OF 7813 FT. R.K.B. PRESSURE TEST CASING TO 3500#. PRESSURE DID NOT HOLD.
6. RAN CORRELATION LOG AND CEMENT BOND LOG. SQUEEZED TOP OF LINER WITH 100 BAGS CEMENT. JOB COMPLETE 8:00 P.M. 9/3/69.
7. PRESSURE TEST CASING TO 3500 PSI FOR 15 MIN. TEST OK.
8. PERFORATION FIRST STAGE DAKOTA WITH ON SHOT/FT. 7724-7746, 7770-7782, 7803-7808. SAND WATER FRAC PERFORATIONS W/70,000# SAND AND 1000# GLASS BEADS AND 73,232 GALS. OF 0.8% KCL WATER.
9. SET 5-1/2" BRIDGE PLUG AT 7680 FT. R.K.B.
10. PERFORATED SECOND STAGE DAKOTA WITH 1 SHOT/FT. 7624-7640 FT. R.K.B. SAND WATER FRAC PERFS WITH 30,000# SAND AND 500# GLASS BEADS WITH 41,832 GALS. OF 0.8% KCL WATER.
11. SET BRIDGE PLUG AT 5180 FT. R.K.B.
12. PERFORATED MESAVERDE WITH 1 SHOT/FT. 5032-5046, 5086-5104, 5110-5128, 5134-5139, 5144-5148 FT. R.K.B. SAND WATER FRAC PERFS WITH 80,000# SAND & 62,580 GALS. OF WATER. (OVER)

18. I hereby certify that the foregoing is true and correct

Original signed by
GILBERT D. NOLAND, JR.

DRILLING SUPERINTENDENT

SEPTEMBER 11, 1969

SIGNED GILBERT D. NOLAND, JR.

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 12 1969

*See Instructions on Reverse Side U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-585229

13. RAN TUBING AND DRILLED OUT BRIDGE PLUGS AT 5180 FT. AND 7680 FT. R.K.B.
14. SET 5-1/2" BAKER MODEL "D" PRODUCTION PACKER AT 7532 FT. R.K.B.
15. RAN 234 YRS. OF 1-1/2" EUE, 2.90#, R-COM-55 TUBING TO DAKOTA.
16. LAMDED IN PACKER AT 7532 FT. R.K.B. BOTTOM OF TUBING AT 7708 FT. R.K.B. RAN 140 FT. 2-1/16" O.D. BLAST JOINTS ACROSS WEBAVAGE PERFORATIONS. BOTTOM AT 5152 FT. AND TOP AT 5012 FT. R.K.B.
17. RAN 155 YRS. OF 1-1/2" 2.75#, R-COM-55 I.D. TUBING TO WEBAVAGE. LAMDED AT 5106 FT. R.K.B. WELL COMPLETED 9/9/69.