

197 FEB 22 PM 1:17

FAIRFAX COUNTY OFFICE
BY SNW

NIMCCD

- 11-23-99 TIH, tag TOC in Chacra csg @ 774'. Load hole w/4.5 bbl wtr. PT Chacra csg to 500 psi, failed. TIIH to 197' in Chacra csg. Plug #5: pump 20 sx Class "B" neat cmt w/2% calcium chloride down csg & out bradenhead. Displace to surface. Circ 1 bbl cmt to surface. TOOH. WOC. TIH, tag TOC inside Chacra csg @ 19'. TOOH. TIH, perf 2 sqz holes in Pictured Cliffs csg @ 897'. TOOH. TIH w/cmt retainer, set @ 838'. TOOH. Load hole w/7 bbl wtr. PT Pictured Cliffs csg to 500 psi, failed. Establish injection. Plug #6: pump 58 sx Class "B" neat cmt below cmt retainer. Pump 5 sx Class "B" neat cmt above cmt retainer inside csg @ 657-838'. No circ out csg. TOOH. SDON. (Herman Lujan, BLM on location).
- 11-24-99 TIH, tag TOC in Pictured Cliffs csg @ 600'. TOOH. Load Pictured Cliffs csg w/wtr. PT csg to 500 psi, failed. TIH, perf 3 sqz holes @ 193'. TOOH. Establish circ down csg & out bradenhead w/6 bbl wtr. Plug #7: pump 87 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Set dry hole marker w/15 sx Class "B" neat cmt. RD. Rig released. (Herman Lujan, BLM on location). Well plugged and abandoned 11-24-99.