

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

940' FSL, 1990' FWL, Sec. 1, T-26-N, R-4-W, NMPM

5. Lease Number

Jic/Contract 101

6. If Indian, All. or
Tribe Name

Jicarilla Apache

7. Unit Agreement Name

8. Well Name & Number

Jicarilla 101 #3

9. API Well No.

30-039-20294

10. Field and Pool

Tapacito Pict Cliffs/
Blanco MV/Basin DK

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to recomplate the subject well in the Mesaverde formation according to the attached procedure. A new C-102 plat is attached. The well will then be down hole commingled. A down hole commingle application will be submitted.



14. I hereby certify that the foregoing is true and correct.

Signed
no

Brian W. Davis

(LNPUD) Title Regulatory Supervisor

Date 12/15/00

(This space for Federal or State Office use)

APPROVED BY */s/ Brian W. Davis*

Title Lands and Mineral Resources

Date JAN 11 2001

CONDITION OF APPROVAL, if any:

District I
PO Box 1980, Hobbs, NM 88241-1980
District II
PO Drawer DD, Artesia, NM 88211-0719
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
PO Box 2088, Santa Fe, NM 87504-2088

State of New Mexico
Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION
PO Box 2088
Santa Fe, NM 87504-2088

Form C-102

Revised February 21, 1994

Instructions on back

Submit to Appropriate District Office

State Lease - 4 Copies

Fee Lease - 3 Copies

☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ API Number 30-039-20294		² Pool Code 85920/72319/71599		³ Pool Name Basin Dakota Tapacito Pictured Cliffs/Blanco Mesaverde/	
⁴ Property Code 18557		⁵ Property Name Jicarilla 101			⁶ Well Number 3
⁷ OGRID No. 14538		⁸ Operator Name Burlington Resources Oil & Gas Company			⁹ Elevation 6924' GR

¹⁰ Surface Location

UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
N	1	26N	4W		940'	South	1990'	West	Rio Arriba

¹¹ Bottom Hole Location If Different From Surface

UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County


¹² Dedicated Acres
PC - 160
MV-DK W/320.36

¹³ Joint or Infill

¹⁴ Consolidation Code

¹⁵ Order No.

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED
OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

<div>16</div> <div>Original plat from Fred B. Kerr, Jr. 7-2-69</div> <div>1990'</div> <div>940'</div>	<div>17 OPERATOR CERTIFICATION</div> <p>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief</p> <div> Signature Peggy Cole Printed Name Regulatory Supervisor Title 12-15-00 Date</div>	
	<div>18 SURVEYOR CERTIFICATION</div> <p>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</p> <div>Date of Survey Signature and Seal of Professional Surveyer:</div>	
	Certificate Number	

Sundry Notice Submittal

Well: Jicarilla 101 #3
Unit N, Sec. 1, T26N, R04W

It is intended to recomplete the Mesaverde formation in the existing Dakota/Pictured Cliffs wellbore. A rig will MIRU, ND wellhead, NU BOP, and pull production tubing. A CIBP will be set above the Dakota formation at approximately 7842'.

If adequately isolated by cement, the Mesaverde formation will be perforated and fracture stimulated in the following interval: 5600-6164'. If cement remediation operations are necessary, Burlington Resources will contact the appropriate regulatory agency for approval prior to work initiation.

After stimulation flowback and clean out, tubing will be landed at approximately 100' above PBTD. The well will then produce commingled production from the Mesaverde, Pictured Cliffs, and Dakota formations.

Approved: Bruce W. Boyer
Drilling Superintendent

12-7-00
Date

Approved: Debbie Cole
Regulatory
Sundry needed

12-8-00
Date