rorm approved. 6 BLM, Fmn 1 DE 1 File Budget Bureau No. 1004-0135 SUBMIT IN TRIPLICATE. UNITED STATES Form 3160-5 Expires August 31, 1985 DEPARTMENT OF THE INTERIOR (Other instructions on verse side) (November 1983) 5. LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT Jicarilla Contract 115 6. IF INDIAN, ALLOTTER OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) Jicarilla Ápache 7. UNIT AGREEMENT NAME WELL X OTHER WELL <del>armington resuchoe</del> area Farmington, new mexico 8. FARM OR LEASE NAME 2. NAME OF OPERATOR JEROME P. McHUGH Tribal 9. WBLL NO. 3. ADDRESS OF OPERATOR P O Box 809, Farmington, NM 87499 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT <u>Blanco Mesaverde</u> 1650' FSL - 990' FWL 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 9, T26N, R3W, NMPM 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. NM 7040' GL <u>Rio Arriba</u> Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: WATER SHUT-OFF REPAIRING WELL PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING TRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT\* SHOOTING OR ACIDIZING ABANDON\* SHOOT OR ACIDIZE Status REPAIR WELL CHANGE PLANS (Norg: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \* Due to lack of gas from the Mesaverde, it was isolated from the Dakota with a packer set at 5995' KB. Gas from the Mesaverde was not found to be commercial in this well and the well is under study at this time. This work was performed by Dugan Production in 1977 and 1978. MARI 5 1988 OIL CON. DIV. going is true and correct 18. I beret Field Supt. 3/8/88 DATE TITLE SIGNED James S. Hazen (This spage for Federal or State office use) ACCEPTED FOR RECORD APPROFED BY TITLE CONDITIONS OF APPROVAL, IF ANY: MAR 1 1 1988

\*See Instructions on Reverse Side

FARIMINGTON RESOURCE AREA

5mm