Form 3160-5

## UNITED STATES

SUBMIT IN TRIPLICATE.

rorm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

(No: (Foi	vember 1983) rmagly 9-331)  BUREAU OF, LAND MANAGEMEN  BUREAU OF, LAND MANAGEMEN		5. LEASE DESIGNATION AND SERIAL NO.  Jicarilla Contract 150	
	SUNDRY NOTICES AND REPORTS  (Do not use this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such 1	ON WELLS	Jicarilla Apache	
	OIL- CAS OTHER		N/A 8. PARM OR LEASE NAME	
<b>2</b>	NAME OF OPERATOR		<del></del>	
	Union Texas Petroleum		JICARILLA G	
	ADDRESS OF OPERATOR	(	9. WHLL NO.	
	375 U.S. Highway 64, Farmington, New Mex	ico 87401	9	
- 1	375 U.S. Highway 64, Farmington, New Mex Location of WELL (Report location clearly and in accordance with any See also space 17 below.) At surface	RECEIVED	<sup>10.</sup> "Branco"Mesaverde/ Basin Dakot <u>a/Toc.</u> Gallup	
•	:	11202112	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
-	990' FNL & 1650' FEL	OCT 16 1986	Section 1-T26N-R5W	
14.	PERMIT NO. 15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE	
	7376' G.L.	BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA	Rio Arriba NM	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
	NOTICE OF INTENTION TO:	SUBSEQU	BNT ESPORT OF:	
	TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
	FRACTURE TREAT X MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CABING	
	BHOOT OR ACIDIZE X ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT*	
	REPAIR WELL CHANGE PLANS	(Other)	of multiple completion on Well etion Report and Log form.)	
	-(Other)	Completion or Recomple	ction report and roll form.	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

1. MIRUSU. TOH w/1-1/2" MV tbg. TOH w/1-1/2" DK tbg & pkr. Remove permanent pkr assembly.

Set BP @ 7600'. Perf Gallup 7835'-7842'. Break down perfs w/acid and frac w/50,000# sand.

Clean out after frac w/drill gas, drill BP & clean out to PBTD 8535'. 3.

Land 1-1/2" tbg @ 8500'. Commingle production from Blanco Mesaverde, Tocito Gallup and Basin Dakota as per N.M.O.C.D. Order R-8321.



-		The state of the s
		ADDROVED
is. I hereby certify that the foregoing is true and cor	rect	TO VED
SIGNED THE Lippin	TITLE Production Engineer	DATE 10/15/86
(This space for Federal or State office use)		0000
APPROVED BY	TITLE	DATE 1 1986
CONDITIONS OF APPROVAL, IF ANY:		Potaskella
1 2		FARMINISTER ACCOUNTS NATEA
	*See Instructions on Reverse Side	THE MESON WE THEN
	HIMUUU	