UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on	Wells
1. Type of Well GAS	5. Lease Number SF-078879 6. If Indian, All.or Tribe Name
2. Name of Operator Meridian Oil Inc.	7. Unit Agreement Name Canyon Largo Unit
3. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505)326-9700	8. Well Name & NumberCanyon Largo Unit #1809. API Well No.
4. Location of Well, Footage, Sec, T, R, M. 890'N, 800'E Sec.23, T-25-N, R-7-W, NMPM	10.Field and Pool Ballard Pictured Cliffs 11.County and State Rio Arriba County, NM
<pre>x Notice of Intent</pre>	Action Change of Plans New Construction
<u>x</u> Casing Repair	<pre> Non-Routine Fracturing Water Shut Off Conversion to Injection</pre>
13. Describe Proposed or Completed Operations It is intended to repair a casing leak in the suffollowing manner: MOL&RU. TOOH w/tbg & pkr. Set RBP above the Piand squeeze the leak in the 2 7/8" csg w/Class squeeze and PT to 400#. Pull RBP and TIH w/tbg Return well to production.	ctured Cliffs. Isolate 'B" neat cmt. Drill out
DECO 6 1991.	10 No (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
TON. DIV.	7 PH 28
14. I hereby certify that the foregoing is true Signed Agay Maapuel (LS) Title Regulatory	
(This space for Federal or State office use) APPROVED BY TITLE	báro
CONDITION OF APPROVAL, IF ANY:	