5-USGS 1-McHug	h 1-NWP	I - File					ļ	1	
Form 9-331 (May 1963)	DEPART	UNITED STA MENT OF TH SEOLOGICAL S	IE INTERI	SUBMIT IN TRIPLICAT (Other instructions on verse side)	5. LEASE	Form approve Budget Buren DESIGNATION	u No. 42	R1424.	
		ICES AND R		N WELLS uck to a different reservoir.		DIAN, ALLOTTEE		E NAME	
I. OIL GAS WELL OTHER						Jicarilla Apache 7. UNIT AGREEMENT NAME			
2. NAME OF OFERATOR Jerome P. McHugh						8. FARM OR LEASE NAME Tiger			
3. ADDRESS OF OPERATOR P. O. Box 234, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						9. WELL NO.			
See also space 17 below.) At surface 1450 FNL, 1450 FEL						Tapacito P.C. 11. SEC., T., R., M., OR BLE, AND			
1450 INC) 1450 I EE						Sec. 21, T26N, R3W			
14. PERMIT NO.	TENUT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7129 GR					Arriba		.M.	
16.	Check Ap		o Indicate N	ature of Notice, Report, or	Other Da				
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	F .	PULL OR ALTER CASI MULTIPLE COMPLETE ABANDON® CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report resu Completion or Reco	X	REPAIRING W ALTERING CA ABANDONMEN	SING		
	fill up, 0.D. 9.5# 100 sacks per sack, cementing Followed	conditioned K-55 8R ST 40-60 (308 good mud r , maximum c	hole, la &C CF&I ca cu. ft.) eturns wh ementing p OO gal. ad	d Density log. Wen id down drill pipe. asing set at 3889' plus 100 sacks Cla ile cementing, work pressure 950 psi. cetic acid. Float	Ran II RKB. Ce ss "C" 7 ed casir P.O.B. n	9 jts. 4 emented w 7 1/2# sa ng okay w nidnight	ith it hite il-24- hut-i	- 72.	
SIGNED	the foregoing is signed by	T. A. Dugan	TITLE	Engineer		DIST.	4	<i>/</i>	
(This space for Feder									