

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME JICARILLA APACHE
2. NAME OF OPERATOR SOUTHERN UNION PRODUCTION COMPANY	8. FARM OR LEASE NAME JICARILLA "D"
3. ADDRESS OF OPERATOR P. O. Box 808, FARMINGTON, New Mexico 87401	9. WELL NO. 11
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FT. FROM THE NORTH LINE AND 1190 FT. FROM THE EAST LINE.	10. FIELD AND POOL, OR WILDCAT TAPACITO PICTURED CLIFFS EL ANCHO DE SAVERDE
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7155 FT. R.K.B.
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 29, T-26N, R-3E, N.M.P.M.
	12. COUNTY OR PARISH RIO ARriba
	13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) SPUDDING ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. SPUDDED 13-3/4" SURFACE HOLE AT 6:30 P.M., 10/24/72. DRILLED TO T.D. OF 273 FT. R.K.B.
2. RAN 7 JOINTS OF 9-5/8", 32.30#, H-40 SURFACE CASING. LANDED AT 269 FT. R.K.B. CEMENTED W/225 BAGS OF CLASS "A" CEMENT. PLUG DOWN AT 3:30 A.M., 10/25/72. CEMENT CIRCULATED TO SURFACE.
3. NIPPLED UP AND PRESSURE TESTED SURFACE CASING AND B.O.P. TO 800 PSI FOR 10 MINUTES. TEST OK.
4. DRILLED OUT FROM UNDER SURFACE CASING WITH 8-3/4" HOLE AT 4:00 P.M., 10/25/72.



18. I hereby certify that the foregoing is true and correct

Original signed by

SIGNED Dan R. Collier
DAN R. COLLIER

TITLE OFFICE MANAGER

DATE NOVEMBER 15, 1972

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

RECEIVED
DATE _____

NOV 17 1972

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of starting, any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

