

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: September 30, 1990

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator

**Amoco Production Company Melissa Velasco-Price**

3. Address and Telephone No.

**P.O. Box 3092 Houston, TX 77253 (281) 366-2548**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**790' FSL & 940' FEL Sec. 31 T26N R5W Unit M**

5. Lease Designation and Serial No.

**Jicarilla Apache 155**

6. If Indian, Allottee or Tribe Name

**Jicarilla Apache**

7. If Unit or CA, Agreement Designation

8. Well Name and No.

**Jicarilla Contract 155 24**

9. API Well No.

**30-039-20570**

10. Field and Pool or Exploration Area  
**Blanco Mesaverde/Otero Chacra**

11. County or Parish, State

**Rio Arriba New Mexico**

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection

**Downhole Commingle**

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

08/29/00 MIRUSU Blow well down. NDWH, pulled on short string to make sure it was loose, NUWH. SDFN. TOH w/112 JTS of 1 1/4" pipe, laying down. NDBOP, pull on long string. LD/donut, NUBOP. RU Slickline, pull plug out. Secure well for night. Blow well down pump 5 BBLS to kill TBG. TOH tallying pipe. Waited for perforated subs. Secure well for night. SD. Blow well down. Pump 30BBLS to kill well. THW/mule shoe, 1 JT 4' perf sub F/nipple, 156 JTS. Tag bottom, lay down 8 JTS. Land TBG w/149 JTS. @ 4908'. NDBOP, JUWH. Secure well for night. SD. Pour rope socket, swab well. Fluid level @ 5100'. Made 4 swab runs, recover 6 BBLS. Rig swab down.

RDMOSU Rig Released 9/5/00 @ 11:00 hrs.

14. I hereby certify that the foregoing is true and correct

Signed Melissa Velasco-Price Title **Permitting Assistant**

Date **10/02/00**

(This space for Federal or State office use)

Approved by Brian W. Davis Title **Lands and Mineral Resources**

Date **OCT 13 2000**

Conditions of Approval, if any: